

The background of the cover is a technical drawing of a high-pressure cell, rendered in white lines on a blue background. The drawing shows a cross-section of the cell, including a central sample chamber, a gasket, and various support structures. The drawing is composed of several rectangular and circular components, some with hatching to indicate different materials or sections. The overall style is that of a scientific or engineering diagram.

# Phase Transitions in Solids Under High Pressure

V. D. Blank *and* E. I. Estrin



CRC Press  
Taylor & Francis Group

CRC Press  
Taylor & Francis Group  
6000 Broken Sound Parkway NW, Suite 300  
Boca Raton, FL 33487-2742

© 2014 by CISP  
CRC Press is an imprint of Taylor & Francis Group, an Informa business

No claim to original U.S. Government works

Printed on acid-free paper  
Version Date: 20130910

International Standard Book Number-13: 978-1-4665-9424-1 (Hardback)

This book contains information obtained from authentic and highly regarded sources. Reasonable efforts have been made to publish reliable data and information, but the author and publisher cannot assume responsibility for the validity of all materials or the consequences of their use. The authors and publishers have attempted to trace the copyright holders of all material reproduced in this publication and apologize to copyright holders if permission to publish in this form has not been obtained. If any copyright material has not been acknowledged please write and let us know so we may rectify in any future reprint.

Except as permitted under U.S. Copyright Law, no part of this book may be reprinted, reproduced, transmitted, or utilized in any form by any electronic, mechanical, or other means, now known or hereafter invented, including photocopying, microfilming, and recording, or in any information storage or retrieval system, without written permission from the publishers.

For permission to photocopy or use material electronically from this work, please access [www.copyright.com](http://www.copyright.com) (<http://www.copyright.com/>) or contact the Copyright Clearance Center, Inc. (CCC), 222 Rosewood Drive, Danvers, MA 01923, 978-750-8400. CCC is a not-for-profit organization that provides licenses and registration for a variety of users. For organizations that have been granted a photocopy license by the CCC, a separate system of payment has been arranged.

**Trademark Notice:** Product or corporate names may be trademarks or registered trademarks, and are used only for identification and explanation without intent to infringe.

**Visit the Taylor & Francis Web site at**  
**<http://www.taylorandfrancis.com>**

**and the CRC Press Web site at**  
**<http://www.crcpress.com>**

# Contents

<b>Preface</b>	<b>vii</b>
<b>I. Introduction: Phase equilibria and kinetics of phase transformations under high pressure</b>	<b>1</b>
1.1. One-component system	5
1.2. Two-component systems	25
References	38
<b>1. Equipment and methods for the study of phase transformations in solids at high pressures</b>	<b>44</b>
1.1. Equipment	44
1.1.1. Hydrostatic pressure	44
1.1.1.1. <i>Producing a high-pressure gas environment</i>	44
1.1.1.2. <i>Generation of high pressure in a fluid</i>	46
1.1.2. Quasi-hydrostatic pressure	47
1.2. Apparatus for the study of phase transitions under pressure in solid by the shear method	47
1.2.1. Chamber for shear under pressure to 25 GPa with diamond anvils of the 'carbonado' type and WC-Co alloys	49
1.2.1.1. <i>High-pressure chamber for shear deformation of solids up to 25 GPa in the range 77–600 K</i>	49
1.2.1.2. <i>A chamber with spherical bearings for shear deformation under pressure to 25 GPa</i>	52
1.2.2. Chambers for shear under pressure with anvils made of natural diamond single crystals	58
1.2.2.1. <i>Diamond chamber for shear under pressure to 43 GPa</i>	58
1.2.2.2. <i>Diamond chamber for shear under pressure to 86 GPa</i>	63
1.2.2.3. <i>Large chamber of the piston-cylinder type for the study of solids at pressures up to 2.5 GPa in the temperature range 77–300 K under shear strain</i>	65
1.3. Methods of investigation of phase transformations at high pressures	68
1.3.1. Magnetometric method	69
1.3.2. Dilatometric method	70
1.3.3. Measurement of electrical resistance under conditions of shear deformation	73
1.3.4. Determination of the deformation work	74

1.3.5. The study of luminescence $\text{Al}_2\text{O}_3:\text{Cr}^{3+}$ in non-hydrostatic compression and plastic flow under pressure	75
1.3.6. Methods of treatment of substances by hydrostatic and quasi-hydrostatic pressure	83
1.3.7. Structural methods of studying solids subjected to shear deformation under pressure	85
1.3.8. Other methods	86
References	86
<b>2. Phase transformations of carbon and boron nitride at high pressure and deformation under pressure</b>	<b>88</b>
2.1. Phase transitions in carbon and boron nitride (review)	90
2.2. Experimental study of phase transformations in carbon and boron nitride in shear under pressure	93
2.2.1. Carbon	93
2.2.2. BN	105
References	122
<b>3. Phase transitions in Si and Ge at high pressure and deformation under pressure</b>	<b>123</b>
References	145
<b>4. Polymorphic <math>\alpha</math>-<math>\omega</math> transformation in titanium, zirconium and zirconium-titanium alloys</b>	<b>147</b>
4.1. Investigation of $\alpha$ - $\omega$ transformation in Ti and Zr in shear under pressure	154
4.2. Ti-Zr alloys	157
References	164
<b>5. Phase transformations in iron and its alloys at high pressure</b>	<b>166</b>
5.1. Polymorphic $\gamma$ - $\alpha$ transformation in iron under pressure	166
5.2. $\alpha$ - $\epsilon$ transformation in iron	173
5.3. $T_0$ - $p_0$ - $c$ diagram with metastable equilibria of iron-based alloys	177
5.3.1. $T_0$ - $p_0$ - $c$ diagram of Fe-Ni alloys	179
5.4. $\gamma$ - $\alpha$ martensitic transformation in a magnetic field	182
5.4.1. Effect of magnetic field on the athermal martensitic transformation	183
5.4.2. Effect of the magnetic field on the isothermal martensitic transformation	186
References	188
<b>6. Phase transformations in gallium and cerium</b>	<b>191</b>
6.1. Gallium	191
6.2. Cerium	193
6.2.1. Isomorphic $\gamma \rightarrow \alpha$ transition in cerium at $T = 300$ K	193

6.2.2. The influence of shear deformation on the $\gamma \leftrightarrow \alpha$ phase transition in cerium	195
References	198
<b>7. On the possible polymorphic transformations in transition metals under pressure</b>	<b>199</b>
References	202
<b>8. Pressure-induced polymorphic transformations in A<sup>I</sup>B<sup>VII</sup> compounds</b>	<b>204</b>
8.1. Polymorphic transformation of rubidium and potassium halides under pressure	204
8.2. Polymorphic transformation in RbI and KCl under pressure at low temperatures	210
8.3. The influence of shear deformation on the B1–B2 transition in KCl and RbCl	218
8.3.1. KCl	218
8.3.2. RbCl	219
8.4. Polymorphic transformation in ScF <sub>3</sub> under pressure	221
References	226
<b>9. Phase transformations in A<sup>II</sup>B<sup>VI</sup> and A<sup>III</sup>B<sup>V</sup> semiconductor compounds</b>	<b>228</b>
9.1. Polymorphic transformation in A <sup>II</sup> B <sup>VI</sup> compounds (CdS and HgTe)	228
9.1.1. CdS	228
9.1.2. HgTe	232
9.2. Polymorphic transformation in A <sup>III</sup> B <sup>V</sup> compounds (InSb and GaSb)	234
9.2.1. InSb	234
9.2.1. The influence of deformation on the phase transition in InSb under pressure	245
9.2.2. GaSb	248
References	254
<b>10. Effect of pressure on the kinetics of phase transformations in iron alloys</b>	<b>256</b>
10.1. The kinetics of the polymorphic $\gamma$ – $\alpha$ transformation in Fe–Cr under pressure	259
10.1.1. $T_0$ – $p$ diagram of Fe–Cr alloys	260
10.1.2. The kinetics of the $\gamma$ – $\alpha$ transformation	262
10.2. The kinetics of the polymorphic $\gamma$ – $\alpha$ transformation in Fe–Ni alloys under pressure	266

10.3. The kinetics of austenite transformation of steel under pressure	276
10.3.1. Pearlite transformation	277
10.3.2. Bainite transformation	283
References	286
<b>11. Transformations during deformation at high pressure</b>	<b>289</b>
11.1. Phase transformations during deformation	289
11.2. Martensitic transformation during deformation	293
11.3. Effect of preliminary plastic deformation on the kinetics of the polymorphic ( $\gamma$ - $\alpha$ ) and pearlite transformations	300
11.4. The formation of solid solutions in shear strain deformation conditions	302
11.4.1. The formation of solid solutions in the Ti-Zr system under shear deformation	306
11.5. The formation of compounds in Fe-X alloys in shear under pressure	315
11.5.1. Fe-Al	315
11.5.2. Fe-Co and Fe-C systems	319
11.5.2.1. Fe-Co alloys	320
11.5.2.2. Fe-C alloys	322
11.6. Compaction and sintering in deformation under pressure	324
11.6.1. The influence of shear deformation on the process of cold sintering of molybdenum under pressure	326
References	332
<b>12. Effects due to phase transformations at high pressure</b>	<b>334</b>
12.1. The effect of pressure redistribution during phase transitions	334
12.1.1. The effect of pressure redistribution due to phase transition in potassium chloride initiated by shear	334
12.1.2. The effect of pressure redistribution due to phase transition in KCl being initiated by the thermal method	337
12.1.3. On the nature of the effect of pressure redistribution during phase transitions	340
12.2. Thermal effects of the polymorphic transformation in RbCl under pressure	344
12.3. Amorphization during deformation at high pressure	349
12.4. Virtual melting of hydrogen and elements of group VIII at negative pressure	352
References	355
<b>13. Kinetics and hysteresis in high-temperature polymorphic transformations under pressure</b>	<b>357</b>
13.1. Kinetics of high-temperature polymorphic transformations at high pressure	360

13.2. Hysteresis of high-temperature polymorphic transformations under pressure	370
13.3. On the lower temperature boundary of high-temperature polymorphic transformations	377
References	380
<b>14. Hysteresis and kinetics of low-temperature polymorphic transformations under pressure</b>	<b>382</b>
14.1. Hysteresis of the low-temperature polymorphic transformations under pressure	382
14.2. On the nature of low-temperature reactions	388
14.2.1. The stability of the initial phase during martensitic transformation	392
14.2.2. Athermal nucleation and athermal crystal growth of a new phase	405
14.3. Kinetics of thermally activated low-temperature transformations	410
14.4. The shape of hysteresis lines of low-temperature transformation and fully isothermal martensitic transformation	416
14.5. Various structural and kinetic types of polymorphic transformations	420
References	421
<b>15. Kinetics of phase transformations under pressure and the synthesis of high-pressure phases</b>	<b>424</b>
15.1. On the mechanism of high-temperature polymorphic transformations	424
15.2. Kinetics of high-temperature and thermally activated low-temperature transformations in the isobaric–isothermal conditions	425
15.3. The dependence of the enthalpy of activation of high-temperature polymorphic transformations on pressure	426
15.4. The temperature limit of stability of high-pressure phases at normal pressure	430
15.5. The kinetics of phase transformations under pressure and the synthesis of high-pressure phases	432
References	435
<b>Conclusions</b>	<b>436</b>
<b>Index</b>	<b>438</b>